

Sensor Extension Cable

For Strain Gauge Sensors or LVDTs



P-892.xx

- Plug (right): FFA.0S.304.CLAC32;
- Socket (left): PCA.0S.304.CLLC32
- Cable: 4 wires; ~ Ø 0,20 mm; #32 AWG (american) ~ #35 SWG (british)
- PVC-Isolation
- Different cable length available

Ordering Information

P-892.01

Extension Cable, for Strain Gauge Sensors, LEMO connector(s), 1 m

P-892.02

Extension Cable, for Strain Gauge Sensors, LEMO connector(s), 2 m

P-892.03

Extension Cable, for Strain Gauge Sensors, LEMO connector(s), 3 m

P-892.05

Extension Cable, for Strain Gauge Sensors, LEMO connector(s), 5 m

P-892.10

Extension Cable, for Strain Gauge Sensors, LEMO connector(s), 10 m

P-892.15

Extension Cable, for Strain Gauge Sensors, LEMO connector(s), 15 m

P-892.VA

Vacuum Feedthrough strain gauge sensor, to 10^{-6} hPa, 100 °C, LEMO connector(s), incl. air side Cable, 2 m